



## WATER WELL LOG & DRILLING REPORT

Ohio Department of Natural Resources  
Division of Geological Survey  
Phone: 614-265-6740

Well Log Number: 798476

### Original Owner & Location

Original Owner Name: *PAT BARNETT*

County: *STARK*

Address: *2107 DOWNING ST*

City:

Location Number:

Latitude: *40.68333*

Township: *PIKE*

State: *OH*

Location Map Year:

Longitude: *-81.39481*

Section Number:

Zip Code:

Location Area:

### Construction Details

Borehole Diameter 1: *in.*

Casing Diameter 1: *5 in.*

Casing Height Above Ground: *ft.*

Date of Completion: *06/27/1994*

Drilling Company Name: *MID-AMERICA  
RECOVERY SERVICE*

Borehole Depth 1: *100 ft.*

Casing Length 1: *100 ft.*

Aquifer Type: *SHALE*

Total Depth: *100*

Depth to Bedrock: *0 ft.*

Casing Thickness 1: *in.*

Well Use: *DOMESTIC*

### Well Test Details

Static Water Level: *39 ft.*

Drawdown: *1 ft.*

Test Rate: *9 gpm*

Test Duration: *1 hrs.*

Associated Documents:

### Comments

### Drilling Log

Formations:	From:	To:
FILL MATERIAL	0	25
SHALE & COAL	0	25
CLAY	0	25
CLAY & SHALE	25	40
SHALE	40	45
CLAY	45	50
SHALE	50	51
WATER AT	0	51
LIMESTONE	51	54
SHALE	54	56
LIMESTONE	56	58
SHALE	58	70
WATER AT	0	70
LIMESTONE	70	78
SHALE	78	100
WATER AT	0	100